





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

Position



- 1 = A 860 425 XX
- 3 = A 962 998 NU (2x)
- 4 = A 860 426 XX
- 5 = A 860 427 XX
- 6 = A 963 427 NU
- 7 = A 962 229 NU
- 8 = A 962 230 NU
- 10 = A 963 432 NU
- 11 = A 963 400 NU
- 14 = A 960 127 XX
- 16 = A 962 594 NU (2x)
- 17 = A 961 810 NU (2x)
- 18 = A 962 595 NU (2x)
- 20 = A 960 914 XX
- 21 = A 960 916 XX (2x)
- 23 = A 963 823 XX
- 24 = A 961 640 NU (2x)
- 25 = A 960 395 NU
- 25a=A 960 196 NU
- 26 = A 963 651 AT
- 27 = A 961 810 NU (2x)
- 28 = A 961 471 XX
- 29 = A 963 667 NU
- 30 = A 961 810 NU (2x)
- 32 = A 962 594 NU (2x)
- 33 = A 962 595 NU (2x)



A 4052




A 4048





ACTIVE
A4046.. A4048.. A4050.. A4052..



0908 / A 865 687
 (+ A 865 612)
 Made in Germany




A 4050






A 4046



Ideal Standard
 Roentgenstrasse 9
 54516 Wittlich
 Germany





	P	bar		MAX. 10		5		Q (3 bar)
	T	°C		MAX. 80		65		I/min 20,5
						40		

